

STANWOOD-CAMANO SCHOOL DISTRICT #401 CITIZENS ADVISORY COMMITTEE		PROSPECTIVE PROJECT INFORMATION		Prioritized - Round 1		MEETING DATE: MARCH 30, 2021	
District Priority Project (Time Sensitive)		District Priority Project (Time Sensitive)		Priority:		1 = MUST DO 2 = SHOULD DO 3 = NICE TO DO	
ITEM	SCHOOL	ITEM DESCRIPTION	PRIORITY	DISTRICT COMMENTS	NOTES		
SCSD		District wide window blind replacement.	1	This is a high priority for all schools and is a safety issue on the lower floors.			
UES		Dry Sprinkler lines at boiler room. Replace rusting pipe.	1				
EBE		Dry Sprinkler lines at kindergarten play area. Replace rusting pipe.	1				
EBE		Boiler Replacement.	1				
TCE		Additional fencing around site to control foot traffic during school hours.	1				
TCE		Remove (4) operable partitions between classrooms	1	NEW. Operable partitions offer limited sound isolation. Affects learning environment in eight classrooms.			
CEC		New Roof.	1	Evaluated CES/EBE/UES with roofing consultant. CES is in need of roofing replacement in the next 3-5 years (as soon as possible).			
CEC		Boiler Replacement.	1				
SES		Updated intercom.	1				
SES		Sidewalk between wings repoured and canopy updated for seismic.	1				
PSMS		Safety fencing and gate at bus drive.	1				
PSMS		Door security similar to elementary schools.	1				
PSMS		Portable maintenance including roofing, paint and repair siding, replace ramps.	1				

One community dedicated to the success of each student.

ITEM	SCHOOL	ITEM DESCRIPTION	PRIORITY	DISTRICT COMMENTS	NOTES
42	SMS	Continue window replacement with blinds and wall repair.	4	\$\$ from 19-22 Budget	
	SMS	PA speaker/system replacement.	1	Currently utilizing a hobbled together system with some speakers not working. System needs to be evaluated.	
	SMS	Bleacher replacement. No safety rails. No longer able to open without someone pulling on bleacher to guide.	1		
	SMS	Re-roof maintenance shed.	1	(Maintenance request)	
	SMS	Gym floor finish.	1		
	SMS	Lunch room floor replacement Approx 5,000 SF.	1.5	This flooring was laid over the original gym flooring.	
4	UES	Add access from Rm C34 to Rm C37, AV Storage for Assist changing table. Add sink.	4.5	\$\$ from 19-22 Budget	
5	UES	Add ADA automatic door openers at four locations.	4.5	\$\$ from 19-22 Budget	
	UES	Fencing at portables to restrict access from parking lot.	1.5		
	TRANS	Parking lot replacement.	2		
	UES	Extend track around ballfields for wheelchair	2		
	TCE	Add shower to health room toilet.	2	For student that have accidents at school and those students without regular access to showers.	
	UES	Computer lab renovation into classroom space.	2		
	UES	Add sink and casework.	2		
	UES	Parking lot/playground paving repair.	2		
24	UES	Hallway flooring replacement.	2		
	UES	Awning over drop-off/pick-up door from gym.	2		
	UES	Remove computer lab and reconfigure as classroom.	2		
	UES	Entry and corridor floor tile replacement, approximately 25,000 SF.	2		
48	SMS	Parking lot replacement.	2		
14	TCE	Replace (2) wood ramps with aluminum ramps.	2.5		


One community dedicated to the success of each student.

One community dedicated to the success of each student.

ITEM	SCHOOL	ITEM DESCRIPTION	PRIORITY	DISTRICT COMMENTS	NOTES
22	CES	Toilet portable for students using portables.	2.5	150 Students.	
35	SES	New fencing on covered play area.	2.5		
49	SMS	Upgrade dust collection in wood shop and move outside.	2.5		
32	SES	Clock replacement.	2.5		
31	SES	Stage carpet and curtain replacement.	3		
18	CES	Add (2) staff toilets.	3	Building has (2) staff toilets and 60 staff.	
20	CES	Dumpster enclosure modification.	3	WM has to drive on the playground to empty dumpsters.	
26	CES	Replace HVAC unit at (2) portables.	3		
33	SES	Classroom carpeting.	3	Classrooms are not carpeted currently.	
34	SES	Walking path for K-5 and SPED pre-school.	3		
N2	SES	Pre-school play area	3	NEW. Separate play area for pre-school.	
	PSMS	Boiler Replacement.	3		
	SMS	Cooking Lab - add exhaust at seven ranges.	3		
50	SMS	Mitigate and remove old Saratoga science building.	3	This building is not useable. Cost to rehabilitate would be excessive.	
51B	SMS	Maintenance shop add concrete floor, replace siding	3		
7	UES	Replace carpet in portable.			Maintenance item
8	UES	Gutter repair.		Some areas are leaking. UES will need a full roof replacement in 5-8 years.	Maintenance item
13	TCB	Remove computer lab and reconfigure as classroom.			Maintenance item
15	TCB	Boiler Replacement			Can wait for next levy
27	SES	Exterior paint at doors and columns.			Maintenance item
39	PSMAS	STEM shop (could be same space as above).			Not a CP item

Stanwood-Camano School District No. 401  
 Capital Projects Facilities & Technology Levy 2023-26

Allocation of Levy Funds 2023-26



Location	Description	Proj Cost	Total Cost	% of Total
District Wide	Technology	TBD	5,173,139.00	50%
District Wide	Building Repairs	TBD	2,069,255.40	20%
District Wide	Safety	TBD	3,103,883.10	30%
Total Levy Amount			10,346,277.50	100%